Work Order May 12, 2010 10:2										Page
Revision ID: Item Name: Str Start Date: 12. Required Date: 18.	SI 9279-011 robe Power Supply Relocation 2/05/2010 Start Qty: 3.00 8/05/2010 Req'd Qty: 3.00		Accept	Cust Item I Customer:				Setup	Start Stop	
	Process Plan:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	t Rej Qty		Reject Insp. Number Stamp
Draw Nbr	Revision Nbr			74.10	······			<u> </u>		
D3246	Rev A1									
DC Document Control	DOCUMENT CONTR Memo Photocopy	OL bluefile and create labels as p	0.00 0.00 per PPP DSI 9279-011 CI	16001 S.S.	5/18		H	Con	CL	10/05/17
110 Packaging Packaging	Pick Kit Memo		0.00			/	10-	7_	<u>/8</u>	(305)
120 QC Quality Control	QC4- 100% Inspect kit Memo	s for completeness	0.00) NG		()		

Dart Aerospace L	_ta
------------------	-----

W/O:			V	VORK ORDER CHANG	ES			3
DATE	STEP	PROCEDURE CHANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:		tegory:	_ NCR: Yes	No DQA:	Date: _	
		lesolution:						
NCR:		V	VORK OR	DER NON-CONFORMA	ANCE (NCR)	v	***************************************
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	on B	Verification	Approval	Approval
		Section A	Chief Eng	Chief Eng	Date	Section C	Chief Eng	QC Inspector
				1				
· · · · · · · · · · · · · · · · · · ·				!				
			:					
				·				
		:						
				i				

Work Order ID 58601

Page 2

May 12, 2010 10:28:33 AM

DSI 9279-011

Accept



Setup Start

Stop



Revision ID:

Item ID:

Item Name: Strobe Power Supply Relocation

Start Date:

12/05/2010

Start Qty: 3.00

Req'd Qty: 3.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

Required Date: 18/05/2010

QC:

Date: SPC (Y/N):

Date:

Draw

Stop

Sequence ID/ Work Center ID

130

Packaging

Packaging

Operation Description

Packaging

Set Up/ **Run Hours**

0.00

MUD

0.00

Identify and pack for shipping as per PPP DSI 9279-011

Rev. Code Qty Qty

Accept

Plan

Reject Reject Number

Insp. Stamp

140

Memo

QC Quality Control QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

		- 						7
W/O:			WO	RK ORDER CHANGI	ES			
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,							
				,				
Part No		PAR #:						
	Reso	olution:	Disposition	:	QA: N/C Clo	sed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR	(*1)		
DATE	STEP	Description of NC	Description of NC Corrective Action		Section B Verification		n Approval Approv	
	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
				: *	:			
		,		,				
					·			

Picklist Print May 12, 2010 10:28:37 AM Work Order ID: 58601 DSI 9279-011 Parent Item: Parent Item Name: Strobe Power Supply Relocation Start Date: 12/05/2010 Required Date: 18/05/2010 B□04.02.26□Add D3121-141 to Step 3□KJ/DS□ Comments: Start Qty: 3.00 Required Qty: 3.00 Component Item ID/ Replacement Mfg/ Bin Primary Last Unit of Qty Route Qty on Qty per Kit Date Item Name Purch Item Location Location Seq ID Measure Hand Item ID Issued Issued Purchased No 120 0.0000 Each D3246-041 No 120 Manufactured Each 4.0000 Mounting Bracket Loc Code Location Loc Qty

140

Each

Loc Qty

249

249

249.0000

Loc Code

ST047

Location

18106

ST291

No

Purchased

MS27039-1-07

Page 1

Status

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			WC	ORK ORDER CHANG	iES			<u>.</u>
DATE STEP		PRO	PROCEDURE CHANGE			Date C	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:						
Resolution: Disposition:					Date: _			
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR)		
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sect Action Description	ion B Sign &	Verification C		Approval QC Inspector
		000.00.17	Chief Eng	Chief Eng	Date	Section C	, Chief Eng	QC Inspector
				,				







DESIGN	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO, C		
CHECKED #	APPROVED -	DRAWING NO. D3246	SHEET	REV. A
DATE		TITLE	***************************************	SCALE
04.04.21		MOUNTING BRACKET		1:4


RELEASED O4.05.07 AF

04.04.21 **NEW ISSUE** 04.06.16 CHANGE RIVET; ADDED C'SINK



D3246-1 FLAT PATTERN





58601

SUBJECT TO AMENDMENT 3.00 (REF) WITHOUT NOTICE WORK ORDER

D3246-041 ASSEMBLY NO ...

NOTES:

MATERIAL: 2024-T3 (QQ-A-250/4) 0.050 THICK (REF. DART SPEC. M2024T3S.050) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED ALL DIMENSIONS ARE IN INCHES


BREAK ALL SHARP EDGES 0.005 TO 0.010

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart	Aero:	space	Ltd
------	-------	-------	-----

W/O:			V	ORK ORD	ER CHANG	ES				<i>5</i>
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					!			:		
					÷					
Part No		PAR #:								
-	Re	esolution:	Disposit	ion:	<u> </u>	_ QA: N/C (closed:		Date:	
NCR:		\	WORK OR	DER NON-C	CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC Section A	Initial		Description	Sign	& Sect	cation ion C	Approval Chief Eng	Approval QC Inspector
			Chief Eng	(Chief Eng	Date			-	
					;					
·										
										
					:			i	,	



	DESIG	14	DRAWN BY	DART AEROSPACE LTE HANKESBURY, ONTARIO, CANADA) .	
1	CHECK	(EQ.,	APPROVED,	DRAWING NO.	ŖEV.	A
		4	#	DSI 9279 SHEE	1 1 OF	2
	DATE			TITLE	SCAL	£
	04.0	4.22		STROBE POWER SUPPLY RELOCATION	IN И	S
	Α		04.04.22	NEW ISSUE		

DART SERVICE INSTRUCTION

REFERENCE ONLY

TO AMEND INSTALLATION DRAWING D350-604 REV. 9 REF. CANADIAN STC: SH90-4

REF. FAA STC: SR00463NY



The purpose of this Service Instruction is to allow for relocation of power supply for the anticollision of the hight so that the D350-604-041 Rear Locker Extender can be properly installed in amora to policy per SB 33.05.

whosen a

- 1) the Graduating gage compartment and remove protective panels.
- 2) Califor and transfer Ø0.129" (3.25mm) holes from D3246-041 Mounting Bracket to skin (1.H) side of the fuselage STA 195 as shown in the sketch. Install D3246-041 Counting Bracket using (8) 21215 DC 24.07J/MS20470AD4 rivets
- If a reconnect tail boom electrical cables LX10E, LX11NE and LX12E from WHELEN A 490 A 55 DF Unit.
- 3) Simple WHELEN A 490 ATS.DF Unit from the original location at STA 203, by removing 2277 BC 040.008L screws.
- 5) 4 ± 04, I/550-604-041 Rear Locker Extender per Dart Installation instruction D350-604.
- Gramma Lightellen A 490 ATS.DF Unit to D3246-041 Mounting Bracket using (4) MS27039arena And (4) AN960JD10 Washers.
- The ourse Cables LX10E, LX11NE and LX12E from the (RH) side to the (LH) side of the all from and re-connect to WHELEN A 490 ATS.DF Unit.
- 6 As it medicables LX10E, LX11NE and LX12E
- 0, which correct operation of anti-collision strobe light.
- a Carlo such up paint per the Aircraft Maintenance Manual to match original finish.
- 4 11 Meth Magage compartment inner protective panels.
- 11. June luggage compartment door.

FARIS (SI

	3. 1	Part Number	Description
	3,5	31 9279-011	STROBE POWER SUPPLY RELOCATION KIT
ِ إحر	P		
Í		02246-041	MOUNTING BRACKET
	1	MS27039-1-07	SCREW
	47	N980JD10	WASHER
	*	The Contraction of State of St	- J.

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01			
BY: K	PROVED ALL ERD (DE #02)		
DATE: CERT. NO.: ISSUE NO.:	04.04.22 SH90-4 #3		

Copyright © 2004 by DART AEROSPACE LTD

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				. '						
			VA	· · · · · · · · · · · · · · · · · · ·						
Part No:		PAR #:	Fault Cate	egory:	_ NCR: Yes No DQA:			_ Date: _	····	
	R	esolution:	ion: Disposition:			losed:		Date:		
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	7)				
DATE	STEP	Description of NC Section A			ion B	Verification		Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign and Date	Sect.	ion C	Chief Eng	QC Inspector	
				i						
					:					
				!						
										
				i						